## ABSTRACT OF THE DISCLOSURE

A method of joining coiled sucker rod in the In its most basic form, the method includes a 5 first step of placing abutting ends of sucker rod in A second step involves face to face relation. positioning a gas burner in proximity to the abutting ends of sucker rod and heating the abutting ends with a hydrocarbon gas flame while applying axial pressure to 10 force the abutting ends together. A third step involves continuing heating and applying pressure until a weld is formed with a bulge formed above the weld which is at least one third of the diameter of the welded rod. A fourth step involves keeping the pressure constant

15 until the weld cools.